

Subwatershed	Location	Station ID	Parameters	Comments
South Branch Shiawassee River	at Davis Road, west of Pinckney Rd	SB-20	Hydro + Fecal/TP	
South Branch Shiawassee River	at Sexton Road betw. County Farm & Yorway	SB-19	Hydro	
South Branch Shiawassee River	at Mason Road, south of I-96	SB-15	Hydro	
South Branch Shiawassee River	at Bowen betw. Brewer and Tooley	SB-14	Hydro	
South Branch Shiawassee River	at Oak Grove betw. Stelzer & Jones	SB-13	Hydro	
South Branch Shiawassee River	at Cohoctah betw. Killen & Wiggins	SB-07	Hydro + Fecal/TP	
Marion and Genoa Drain	at Chilson, south of Beck Rd	MG-18	Hydro + Fecal/TP	General conditions good; riparian veg'n good; tea appearance to streambed
Marion and Genoa Drain	at Chilson, between Grand River and Beck Rd	MG-17	Hydro	This site is a complete mess; completely disturbed
Marion and Genoa Drain	at Peavy betw. I-96 & Alstott	MG-16	Hydro + Fecal/TP	
Bogue Creek	at Nixon north of Golf Club Dr.	BC-12	Hydro + Fecal/TP	
Bogue Creek	at Hughes north of Golf Club Dr.	BC-11	Hydro	
Bogue Creek	at Mack, north of Curdy	BC-10	Hydro	
Bogue Creek	at Curdy, east of Fisher	BC-09	Hydro + Fecal/TP	
Bogue Creek	at Jones, east of Oak Grove, west of Fisher	BC-08	Hydro + Fecal/TP	
Yellow River Drain	at Dean betw. Wiggins & Latson	YR-06	Hydro + Fecal/TP	
Yellow River Drain	at Cohoctah betw. Latson & White	YR-05	Hydro	
Yellow River Drain	at Lovejoy betw. Latson & White	YR-01	Hydro + Fecal/TP	
Cranberry Creek	at Faussett betw. Green & McGuire	CC-04	Hydro + Fecal/TP	
Cranberry Creek	at Center betw. Mack & Argentine	CC-03	Hydro + Fecal/TP	
Cranberry Creek	at Cohoctah betw. White & Gould	CC-02	Hydro + Fecal/TP	
North Ore Creek	at Clyde Road, west of Cullen	NO-08	Hydro + Fecal/TP	Site addition; flashy hydrology noted
North Ore Creek	at Brophy betw. Argentine & Musson	NO-10	Hydro	
North Ore Creek	at Dwyer, east of Musson	NO-09	Hydro	
North Ore Creek	at Dunham, east of Hartland, west of Bullard	NO-07	Hydro + Fecal/TP	Site change; grass dumped in creek d/s; trash (constr. Barrel)
North Ore Creek	at Parshallville/Linden	NO-06	Hydro + Fecal/TP	d/s conditions excellent; u/s is Parshallville Pond impoundment
North Ore Creek	at Hartland, north of Faussett	NO-05	Hydro	
North Ore Creek	at Hogan, east of Green, west of Linden	NO-04	Hydro + Fecal/TP	Flooding problems have been noted here when Lake Shannon dam is opened. Increased sedimentation d/s of here into Hoisington Lake.
Denton Creek	at Foley, west of White Lake Road	DC-03	Hydro	
Denton Creek	at Denton Hill (Fenton Rd), north of White Lake Rd	DC-02	Hydro + Fecal/TP	Decent site d/s; road input significant in terms of sw runoff--a lot of impervious surface here, no buffer between road
Denton Creek	at Linden, betw. Hogan & Bennett Lake Rd	DC-01	Hydro + Fecal/TP	Awesome site--great condition; aquatic plants and fish numerous